

## Solicitors Office Report Details

**Queensland Police Service**  
Report no.: QP2102188900  
Occurrence Type: Non-reportable CAD Event [1851]  
Occurrence time: 24/11/2021 04:24 -  
Reported time: 24/11/2021 04:24  
Place of offence: 232 GIVEN TCE, PADDINGTON, QLD Australia 4064 (Patrol group: CITY CENTRAL, Court Dist./Div.: BRISBANE/CENTRAL, Region: BRISBANE, District: NORTH BRISBANE, Division: BRISBANE CITY, Stats area: 305011454)  
Clearance status: Finalised  
CAD event ID: 000343-24112021  
Summary: CAD Event No: 000343-24112021 Dispatch Address: 232 GIVEN TCE,PADDINGTON,BRISBANE,4064 Reporting Officer: 4025215 Dispatch Type: 401 Address Co-ordinates X: 153.00498867 Y: -27.4616714  
Concluded summary:  
  
*Printed: 09/05/2022 12:22 by 4029406*

**Involved persons:** \_\_\_\_\_

**Involved vehicles:** \_\_\_\_\_

**Involved property:** \_\_\_\_\_

**Modus operandi:** \_\_\_\_\_

**Reports:** \_\_\_\_\_

QPS RTI & PRIVACY UNIT

---

PRIMARY INCIDENT TYPE: 514 - Fire Service

INFORMANT ADDRESS DETAIL: QFES,

INITIAL CAD INCIDENT DETAIL: QFES CALLED DIRECT NUMBER REQUIRING QPS RE SMOKE FROM THE IL - NIL FURTHER INC 341 - ICEMS

INFORMANT NAME: QFES

INFORMANT CONTACT NUMBER: QFES

INFORMANT OTHER CONTACT NUMBER:

CAD SOURCE: QFRS

INCIDENT ADDRESS DETAIL: 232 GIVEN TCE, PADDINGTON, BRISBANE, 4064

---

24/11/2021 04:25:52 Recipient BRC Added

24/11/2021 04:25:52 Recipient BRC-S Added

24/11/2021 04:25:52 Recipient TEL Added

24/11/2021 04:25:52 Address Update - Exact Address Location

24/11/2021 04:25:52 Incident created as partial

24/11/2021 04:25:52 Tag Created as Partial added

24/11/2021 04:25:52 Forms MLP Call Collection FormCLI: \* Source: QFRSDetails: QFES CALLED DIRECT NUMBER REQUIRING QPS RE SMOKE FROM THE IL - NIL FURTHER INC 341 - ICEMS PoliceLink ID:

24/11/2021 04:25:53 Recipient TEL set to Viewed

24/11/2021 04:25:53 Status changed from U - Unviewed to V - Viewed

24/11/2021 04:25:53 Incident viewed by user 4012528 (status changed)

24/11/2021 04:25:53 Recipient TEL set to Unviewed

24/11/2021 04:25:53 Status changed from V - Viewed to U - Unviewed

24/11/2021 04:25:53 Call Collection Form(1) message recorded

24/11/2021 04:25:53 Recipient TEL set to Viewed

24/11/2021 04:25:53 Status changed from U - Unviewed to V - Viewed

24/11/2021 04:25:53 Incident viewed by user 4012528 (status changed)

24/11/2021 04:25:59 Recipient BRC set to Viewed

24/11/2021 04:26:00 PCC Call Taker QFES ON SCENE

24/11/2021 04:26:03 Recipient BRC-S set to Viewed

24/11/2021 04:26:15 PCC Call Taker SUGGEST MERGE WITHTEH ICEMS WHNE PROCESSED

24/11/2021 04:26:17 Tag Incident Approved added

24/11/2021 04:26:21 Incident Broadcast ALL RESOURCES broadcast for 000343-24112021

24/11/2021 04:26:28 PCC Call Taker SOLVE - LLMLM

24/11/2021 04:26:36 Incident Broadcast NC421 ACKNOWLEDGED broadcast for 000343-24112021 to ALL

24/11/2021 04:26:36 Informed of incident 000343-24112021

24/11/2021 04:26:36 Status changed from V - Viewed to A - Assigned

24/11/2021 04:26:50 PCC Call Taker FROM PI VI - CH - IL IS DOMINOS

24/11/2021 04:26:58 Incident is no longer partial

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]Recipient BRC Added

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]Recipient BRC-S Added

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]Recipient TEL Added

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]Address Update - Exact Address Location

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]RSU Incoming Status update from: POL-Q (Q21-A053122). Setting status to: INF

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]Recipient AMB-Q Added

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]RSU Incoming Status update from: AMB-Q (Q21-A053122). Setting status to: REQ

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]Recipient AMB-Q set to Viewed

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]External Agency Queensland Ambulance Service added to Incident

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]ICEMS Message from AMB-QInformant Name: UnknownLocation of offenders: UnknownNumber of offenders: UnknownDescription of offenders: UnknownType of weapons involved: UnknownRisk or threats to officers safety: UnknownNumber of vehicles involved: UnknownDescription of vehicles involved: UnknownScene related information: Not applicableRequesting PSA location: Responding

24/11/2021 04:25:14 [ MERGE from 000341-24112021 ]ACK sent for: IARMessage (Q21-A053122) (04010100202111230625060087857)

24/11/2021 04:25:51 [ MERGE from 000341-24112021 ]Status changed from X - Pre Create to Y - Pre Complete

24/11/2021 04:25:59 [ MERGE from 000341-24112021 ]Routing Coordinate changed from - 27.46141,153.00503 to -27.4616714,153.00498867

24/11/2021 04:25:59 [ MERGE from 000341-24112021 ]Coordinate changed from - 27.46141,153.00503 to -27.4616714,153.00498867

24/11/2021 04:26:00 [ MERGE from 000341-24112021 ]RSU Incoming Status update from: AMB-Q (Q21-A053122). Setting status to: EnRoute

24/11/2021 04:26:00 [ MERGE from 000341-24112021 ]ACK sent for: RSUMessage (Q21-A053122) (04010100202111230625380087859)

24/11/2021 04:26:01 [ MERGE from 000341-24112021 ]QPrime Location QPrime Search requested

24/11/2021 04:26:26 [ MERGE from 000341-24112021 ]QPrime Caller QPrime Search requested

24/11/2021 04:27:08 [ MERGE from 000341-24112021 ]Type changed from ICEMS to 401 - Fire Building

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Informant changed from to QFES

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Informant Address changed from ,,,,,, to BUSINESS ADDRESS NEXT TO DOMINOS,,232 GIVEN TCE,,PADDINGTON,BRISBANE,4064

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Details changed from [ProQA Dispatch] Dispatch Level: 07B02 (Unknown status\Other codes not applicable) Suffix: F (Fire present) Response Text: 1C QFES QPS Age unknown, Gender unknown, Consciousness unknown, Breathing status unknown. Unknown number of patients involved. Problem Description: SMOKE BILLOWING FROM PREMISE JOB FROM QFES - LINKING to \*\*\*REPEAT OF 343\*\*\*[ProQA Dispatch] Dispatch Level: 07B02 (Unknown status\Other codes not applicable) Suffix: F (Fire present) Response Text: 1C QFES QPS Age unknown, Gender unknown, Consciousness unknown, Breathing status unknown. Unknown number of patients involved. Problem Description: SMOKE BILLOWING FROM PREMISE JOB FROM QFES - LINKINGPINR VINR CHNRNO Q PAGESOLVE - MLMLM

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Forms MLP Call Collection FormCLI: \* Source: ICEMSDetails: \*\*\*REPEAT OF 343\*\*\*[ProQA Dispatch] Dispatch Level: 07B02 (Unknown status\Other codes not applicable) Suffix: F (Fire present) Response Text: 1C QFES QPS Age unknown, Gender unknown, Consciousness unknown, Breathing status unknown. Unknown number of patients involved. Problem Description: SMOKE BILLOWING FROM PREMISE JOB FROM QFES - LINKINGPINR VINR CHNRNO Q PAGESOLVE - MLMLMPoliceLink ID:

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Call Collection Form(1) message recorded

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Recipient TEL set to Viewed

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Sending IRA update for incident: 000341-

24112021

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Auto sending RSQ to Agency: AMB-Q

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Status changed from Y - Pre Complete to V - Viewed

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Incident viewed by user 4013154 (status changed)

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Recipient TEL set to Unviewed

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Recipient AMB-Q set to Unviewed

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]Status changed from V - Viewed to U - Unviewed

24/11/2021 04:27:16 [ MERGE from 000341-24112021 ]RSU Sending To: AMB-Q (Q21-A053122) Status: WillAttend

24/11/2021 04:27:20 [ MERGE from 000341-24112021 ]Recipient BRC set to Viewed

24/11/2021 04:27:20 [ MERGE from 000341-24112021 ]Sending IRA update for incident: 000341-24112021

24/11/2021 04:27:20 [ MERGE from 000341-24112021 ]Auto sending RSQ to Agency: AMB-Q

24/11/2021 04:27:20 [ MERGE from 000341-24112021 ]Status changed from U - Unviewed to V - Viewed

24/11/2021 04:27:20 [ MERGE from 000341-24112021 ]Incident viewed by user 4038232 (status changed)

24/11/2021 04:27:23 [ MERGE from 000341-24112021 ]IRA SysAcknowledged: AMB-Q (Q21-A053122) (04010500202111231827160016078)

24/11/2021 04:27:23 [ MERGE from 000341-24112021 ]RSQ Request Sent To: AMB-Q (04010500202111231827160016079)

24/11/2021 04:27:30 [ MERGE from 000341-24112021 ]RSQ SysAcknowledged: AMB-Q (04010500202111231827160016079)

24/11/2021 04:27:34 [ MERGE from 000341-24112021 ]RSQ Status Update Timed Out: AMB-Q (04010500202111231827160016079)

24/11/2021 04:27:34 [ MERGE from 000341-24112021 ]Action Prompt 000341-24112021(3) User acknowledgement not received from AMB-Q (RSQ Status Update Timed Out: 04010500202111231827160016079) displayed to All

24/11/2021 04:27:36 [ MERGE from 000341-24112021 ]RSU SysAcknowledged: AMB-Q (Q21-A053122) (04010500202111231827160016080)

24/11/2021 04:27:36 [ MERGE from 000341-24112021 ]RSQ Request Sent To: AMB-Q (04010500202111231827200016081)

24/11/2021 04:27:43 [ MERGE from 000341-24112021 ]RSQ SysAcknowledged: AMB-Q (04010500202111231827200016081)

24/11/2021 04:27:47 [ MERGE from 000341-24112021 ]RSQ Status Update Timed Out: AMB-Q (04010500202111231827200016081)

24/11/2021 04:27:47 [ MERGE from 000341-24112021 ]Action Prompt 000341-24112021(3) User acknowledgement not received from AMB-Q (RSQ Status Update Timed Out: 04010500202111231827200016081) displayed to All

24/11/2021 04:27:47 [ MERGE from 000341-24112021 ]RSU Incoming Status update from: AMB-Q (Q21-A053122). Setting status to: EnRoute

24/11/2021 04:27:47 [ MERGE from 000341-24112021 ]ACK sent for: RSUMessage (Q21-A053122) (04010100202111230627290087864)

24/11/2021 04:27:54 [ MERGE from 000341-24112021 ]RSU Incoming Status update from: AMB-Q (Q21-A053122). Setting status to: EnRoute

24/11/2021 04:27:54 [ MERGE from 000341-24112021 ]ACK sent for: RSUMessage (Q21-A053122) (04010100202111230627430087865)

24/11/2021 04:28:40 [ MERGE from 000341-24112021 ]Recipient BRC-S set to Viewed

24/11/2021 04:29:00 Recipient AMB-Q set to Viewed

24/11/2021 04:29:00 External Agency Queensland Ambulance Service added to Incident

24/11/2021 04:29:00 Incident merged with 000341-24112021

24/11/2021 04:29:00 RSU Sending To: AMB-Q (Q21-A053122) Status: WillAttend

24/11/2021 04:29:06 RSU SysAcknowledged: AMB-Q (Q21-A053122) (04010500202111231829000016082)

24/11/2021 04:29:45 ACK sent for: RSQMessage (Q21-A053122) (04010100202111230629450087869)

24/11/2021 04:29:45 RSU Sending To: AMB-Q (Q21-A053122) Status: WillAttend

24/11/2021 04:29:52 RSU SysAcknowledged: AMB-Q (Q21-A053122) (04010500202111231829450016083)

24/11/2021 04:32:32 RSU Incoming Status update from: AMB-Q (Q21-A053122). Setting status to: OnScene

24/11/2021 04:32:32 ACK sent for: RSUMessage (Q21-A053122) (04010100202111230632310087877)

24/11/2021 04:33:27 RSU Incoming Status update from: AMB-Q (Q21-A053122). Setting status to: URGENT

24/11/2021 04:33:27 ICEMS Message from AMB-Q501242 CONF SMOKE COMING FROM BUILDING FURTHER TO COME

24/11/2021 04:33:27 ACK sent for: IUMMessage (Q21-A053122)  
(04010100202111230633260087880)

24/11/2021 04:33:32 Status changed from A - Assigned to P - Proceeding

24/11/2021 04:33:32 Status Update NC421 with 4025392, 4037434 Status changed from O - On Air to P3 - Proceeding 3

24/11/2021 04:33:32 NC421 with 4025392, 4037434 Assigned to Incident 000343-24112021

24/11/2021 04:33:32 RSU Sending To: AMB-Q (Q21-A053122) Status: EnRoute

24/11/2021 04:33:33 NC421 (BRC) Welfare Check set to 24/11/2021 05:03:33

24/11/2021 04:33:33 Status changed from P - Proceeding to I - At Incident

24/11/2021 04:33:33 Status Update NC421 with 4025392, 4037434 Status changed from P3 - Proceeding 3 to I - At Incident

24/11/2021 04:33:33 RSU Sending To: AMB-Q (Q21-A053122) Status: OnScene

24/11/2021 04:33:38 RSU SysAcknowledged: AMB-Q (Q21-A053122)  
(04010500202111231833320016084)

24/11/2021 04:33:45 RSU SysAcknowledged: AMB-Q (Q21-A053122)  
(04010500202111231833330016085)

24/11/2021 04:33:45 IUA Sent: AMB-Q (Q21-A053122) (04010500202111231833360016086)

24/11/2021 04:33:52 IUA SysAcknowledged: AMB-Q (Q21-A053122)  
(04010500202111231833360016086)

24/11/2021 04:35:32 Sitrep LATROBE BLOCKED WITH FIRE VEHICLES. ALL IN HAND.  
BUILDING FIRE. DOMINOES

24/11/2021 04:36:45 Recipient DO-BNE Added

24/11/2021 04:37:23 Police (Call Sign) NEED ANOTHER CREW UP HERE PLS

24/11/2021 04:37:29 NC823 with 4040765 Clear from Incident 000324-24112021

24/11/2021 04:37:29 NC823 with 4040765 Assigned to Incident 000343-24112021

24/11/2021 04:37:40 Status Update NC821 with 4021240 Status changed from O - On Air to P3 - Proceeding 3

24/11/2021 04:37:40 NC821 with 4021240 Assigned to Incident 000343-24112021

24/11/2021 04:37:57 Recipient DO-BNE set to Viewed

24/11/2021 04:39:23 NC823 (BRC) Welfare Check set to 24/11/2021 05:09:23

24/11/2021 04:39:23 Status Update NC823 with 4040765 Status changed from P3 - Proceeding 3 to I - At Incident

24/11/2021 04:39:23 NC821 (BRC) Welfare Check set to 24/11/2021 05:09:23

24/11/2021 04:39:23 Status Update NC821 with 4021240 Status changed from P3 - Proceeding 3 to I - At Incident

24/11/2021 04:40:12 Sitrep DIVERTING CARS FROM LATROBE TCE DOWN GUTHRIE ST AS LATROBE IS TOTALLY BLOCKED

24/11/2021 04:40:34 Sitrep DIVERTING CARS FROM GIVEN TCE DOWN GUTHRIE ST AS GIVEN TCE IS TOTALLY BLOCKED

24/11/2021 04:54:41 Status Update NC400 with 4011837 Status changed from O - On Air to P3 - Proceeding 3

24/11/2021 04:54:41 NC400 with 4011837 Assigned to Incident 000343-24112021

24/11/2021 04:54:44 NC400 (BRC) Welfare Check set to 24/11/2021 05:24:44

24/11/2021 04:54:44 Status Update NC400 with 4011837 Status changed from P3 - Proceeding 3 to I - At Incident

24/11/2021 05:01:00 Police (Call Sign) WILL WE REQUIRE TRU VEHICLES AT THIS JOB?

24/11/2021 05:01:47 Police (Call Sign) UNKNOWN HOW LONG IT WILL TAKE REQ TRU VEHICLE UP HERE JUST IN CASE

24/11/2021 05:03:37 Key CALL TO TMC - SENDING TRU FROM 8 MILE PLAINS

24/11/2021 05:05:11 Status Update NC320 with 4027920, 4035405 Status changed from O - On Air to P3 - Proceeding 3

24/11/2021 05:05:11 NC320 with 4027920, 4035405 Assigned to Incident 000343-24112021

24/11/2021 05:05:18 Status Update NC160 with 4007977 Status changed from O - On Air to P3 - Proceeding 3

24/11/2021 05:05:18 NC160 with 4007977 Assigned to Incident 000343-24112021

24/11/2021 05:06:01 NC160 with 4007977 Current Location changed from BRC to STF

24/11/2021 05:13:01 NC160 with 4007977 Current Location changed from STF to BRC

24/11/2021 05:26:03 Recipient DO-BNE Removed

24/11/2021 05:31:44 Location: [153.004657674792, -27.4612446801328]

24/11/2021 05:31:44 NC160 (BRC) Welfare Check set to 24/11/2021 06:01:44

24/11/2021 05:31:44 Status Update NC160 with 4007977 Status changed from P3 - Proceeding 3 to I - At Incident

24/11/2021 06:02:38 NC320 (BRC) Welfare Check set to 24/11/2021 06:32:38

24/11/2021 06:02:38 Status Update NC320 with 4027920, 4035405 Status changed from P3 -



## Proceeding 3 to I - At Incident

24/11/2021 06:05:25 Status Update NC886 with 4027085 Status changed from S - At Station to P3 - Proceeding 3

24/11/2021 06:05:25 NC886 with 4027085 Assigned to Incident 000343-24112021

24/11/2021 06:12:17 Police (Call Sign) OPENED INBOUND LANE GIVEN TCE - STILL CLOSURES ON OUTBOUND FRO A BIT - WILL OPEN SOON

24/11/2021 06:14:50 Status Update NC888 with 4037294 Status changed from O - On Air to P3 - Proceeding 3

24/11/2021 06:14:50 NC888 with 4037294 Assigned to Incident 000343-24112021

24/11/2021 06:22:00 NC400 with 4011837 Current Location changed from BRC to WES

24/11/2021 06:22:20 NC400 with 4011837 Current Location changed from WES to BRC

24/11/2021 06:24:11 Status Update NC400 with 4011837, 4025215 Status changed from I - At Incident to S - At Station

24/11/2021 06:24:11 NC400 with 4025215 Clear from Incident 000343-24112021

24/11/2021 06:24:11 Driver changed from 4011837 to 4025215

24/11/2021 06:24:11 Shift changed from 21-06 to 06-15

24/11/2021 06:30:28 NC888 (BRC) Welfare Check set to 24/11/2021 07:00:28

24/11/2021 06:30:28 Status Update NC888 with 4037294 Status changed from P3 - Proceeding 3 to I - At Incident

24/11/2021 06:30:28 NC886 (BRC) Welfare Check set to 24/11/2021 07:00:28

24/11/2021 06:30:28 Status Update NC886 with 4027085 Status changed from P3 - Proceeding 3 to I - At Incident

24/11/2021 06:33:23 Location: [153.02575683, -27.4735755899998]

24/11/2021 06:33:23 Status Update NC823 with 4040765 Status changed from I - At Incident to S - At Station

24/11/2021 06:33:23 NC823 with 4040765 Clear from Incident 000343-24112021

24/11/2021 06:41:46 Police (Call Sign) BOTH INBOUND & OUTBOUND ARE OPEN - URBAN UTILITIES WORK WILL BE DELAYED UNTIL TONIGHT

24/11/2021 06:43:35 Status Update NC160 with 4007977 Status changed from I - At Incident to O - On Air

24/11/2021 06:43:35 NC160 with 4007977 Clear from Incident 000343-24112021

24/11/2021 06:44:24 Status Update NC888 with 4037294 Status changed from I - At Incident to O -

On Air

24/11/2021 06:44:24 NC888 with 4037294 Clear from Incident 000343-24112021

24/11/2021 06:44:24 Status Update NC886 with 4027085 Status changed from I - At Incident to O - On Air

24/11/2021 06:44:24 NC886 with 4027085 Clear from Incident 000343-24112021

24/11/2021 06:48:12 Finalisation Details NON SUS FIRE - BOTH INBOUND & OUTBOUND LANES OPEN

24/11/2021 06:48:12 Revised Type changed from to 401 - Fire Building

24/11/2021 06:48:12 Officer In Charge changed from to 4025215

24/11/2021 06:48:21 Status Update NC320 with 4027920, 4035405 Status changed from I - At Incident to O - On Air

24/11/2021 06:48:21 NC320 with 4027920, 4035405 Clear from Incident 000343-24112021

24/11/2021 06:48:21 Status Update NC821 with 4021240 Status changed from I - At Incident to O - On Air

24/11/2021 06:48:21 NC821 with 4021240 Clear from Incident 000343-24112021

24/11/2021 06:48:21 Status changed from I - At Incident to F - Filed

24/11/2021 06:48:21 Status Update NC421 with 4025392, 4037434 Status changed from I - At Incident to O - On Air

24/11/2021 06:48:21 NC421 with 4025392, 4037434 Clear from Incident 000343-24112021

24/11/2021 06:49:13 Incident Closed

24/11/2021 06:49:13 Recipient AMB-Q Removed

## Solicitors Office Report Details

### Queensland Police Service

Report no.: QP2102188867  
 Occurrence Type: Fire - Building - Non Suspicious [0915]  
 Occurrence time: 24/11/2021 04:15 -  
 Reported time: 24/11/2021 05:53  
 Place of offence: 232 GIVEN TCE, PADDINGTON, QLD Australia 4064 (Patrol group: CITY CENTRAL, Court Dist./Div.: BRISBANE/CENTRAL, Region: BRISBANE, District: NORTH BRISBANE, Division: BRISBANE CITY, Stats area: 305011454)  
 Clearance status: Finalised  
 Operation name: Intranet Occurrences  
 Summary: Occurrence Type: Fire - Building - Non Suspicious (0915); Occurrence Address: 232 GIVEN TCE, PADDINGTON, QLD, 4064; Victim 1: DOMINOS PIZZA PADDINGTON; Victim 2: BELLE PROPERTY;  
 Concluded summary:

Printed: 09/05/2022 12:19 by 4029406

### Involved persons:

1. Sch4p4(6) / Informant: Owner / Sch4p4(6)
2. Sch4p4(6) / Informant: Owner / Sch4p4(6)
3. BELLE PROPERTY / Victim / 21553864 232 GIVEN TCE, PADDINGTON, QLD Australia 4064 (Patrol group: CITY CENTRAL, Court Dist./Div.: BRISBANE/CENTRAL, Region: BRISBANE, District: NORTH BRISBANE, Division: BRISBANE CITY, Stats area: 305011454) (Land line) 0735108222
4. DOMINOS PIZZA PADDINGTON / Victim / 21989018 232 GIVEN TCE, PADDINGTON, QLD Australia 4064 (Patrol group: CITY CENTRAL, Court Dist./Div.: BRISBANE/CENTRAL, Region: BRISBANE, District: NORTH BRISBANE, Division: BRISBANE CITY, Stats area: 305011454) (Land line) 31095777

### Involved vehicles:

### Involved property:

1. Building materials: Building / Damaged / Occ: QP2102188867
2. Building materials: Door / Damaged / Occ: QP2102188867

### Modus operandi:

1. Location: Commercial. Subtype: Restaurant. Other behavior at scene: Other. Method of escape: Unknown. No. of offenders/suspects: Unknown. Free text keywords: AT THE NOMINATED TIME AND DATE A FIRE WAS REPORTED TO BE OCCURRING IN THE DOMINOS EATERY LOCATED IN GIVEN TERRACE PADDINGTON. THE LOCATION IS A BUILDING SHARED BY 2X TENANT

BUSINESSES. QFRS ATTENDED AND EXTINGUISHED THE FIRE IN THE DOMINOS VICTIM BUSINESS. QFRS WERE REQUIRED TO FORCE ENTRY THROUGH THE FRONT DOOR OF THE SECOND VICTIM BUSINESS (BELLE PROPERTY) AS SMOKE WAS OBSERVED INSIDE. THE QFRS INCIDENT COMMANDER STATED THAT INITIAL ASSESSMENT OF THE LOCATION OF THE FIRE APPEARED TO ORIGINATE FROM THE REAR OF DOMINOS WHERE THERE IS A ELECTRICAL BOX. THE FIRE HAS SEVERELY DAMAGED THE INSIDE OF THE DOMINOS EATERY. THE BELL PROPERTY BUSINESS ONLY SUSTAINED SMOKE DAMAGE AND DAMAGED FRONT DOOR CAUSED BY QFRS EFFECTING ENTRY FIRE INVESTIGATORS YET TO ATTEND AND DETERMINE THE LIKELY CAUSE OF THE FIRE. INITIAL FIRE RESPONSE CREWS STATED THAT THEY DID NOT SEE ANY SIGN OF FORCED ENTRY. ON SPEAKING TO THE OWNER OF DOMINOS, IT WAS STATED THAT STAFF LEFT THE PROPERTY AT 1:AM IT WAS STATED THAT THERE WAS WATER LEAKING THROUGH THE ROOF WHICH CAUSED THE POWER TO GO OUT. IT WAS STATED THAT THE STAFF INTENDED TO LEAVE THE ISSUE UNTIL THE MORNING. QFRS INCIDENT COMMANDER STATED THAT THE WATER LEAK APPEARED TO BE ABOVE THE ELECTRICAL BOX WHICH IS LIKELY TO HAVE CAUSED THE FIRE. <BR/><BR/><U>FIRE REPORT MO DETAILS</U> <BR/>THE LOCATION IS A BUILDING SHARED BY 2X TENANT BUSINESSES. QFRS ATTENDED AND EXTINGUISHED THE FIRE IN THE DOMINOS VICTIM BUSINESS. QFRS WERE REQUIRED TO FORCE ENTRY THROUGH THE FRONT DOOR OF THE SECOND VICTIM BUSINESS (BELLE PROPERTY) AS SMOKE WAS OBSERVED INSIDE. THE QFRS INCIDENT COMMANDER STATED THAT INITIAL ASSESSMENT OF THE LOCATION OF THE FIRE APPEARED TO ORIGINATE FROM THE REAR OF DOMINOS WHERE THERE IS A ELECTRICAL BOX. . FIRE SUPPRESSION ACTIVITY: N/A. WERE OTHER FIRES OCCURRING IN THE AREA AT THE TIME: NO. HAVE SIMILAR FIRES BEEN OCCURRING IN THE GENERAL OR WIDER AREA: NO. WERE ANY FIRE WARNING IN FORCE AT THE TIME: NO. DO YOU THINK THIS MAY BE THE ACT OF A RECIDIVIST OFFENDER : NO..

---

**Reports:**


---

**General report**

Occurrence: QP2102188867 Fire - Building - Non Suspicious [0915]  
@24/11/2021 05:53 (232 GIVEN TCE, PADDINGTON, QLD  
Australia 4064 (Patrol group: CITY CENTRAL, Court  
Dist./Div.: BRISBANE/CENTRAL, Region: BRISBANE,  
District: NORTH BRISBANE, Division: BRISBANE CITY,  
Sta

Task: T2105609604 [Init rpt - Closed] Due: 25/11/2021 06:30  
#4025392 PRESTON, J. ->#4025392 PRESTON, J. [Low]  
QPS Investigative Task Workflow Initial Report Task and  
Start Point QP2102188867 Fire - Building - Non Suspicious  
[0915] @24/11/2021 05:53 (232 GIVEN T  
#4025392 PRESTON, J.

Author: #4025392 PRESTON, J.  
Report time: 24/11/2021 05:53  
Entered by: #4025392 PRESTON, J.  
Entered time: 24/11/2021 06:30  
Remarks: Occurrence Type: Fire - Building - Non Suspicious (0915);  
Occurrence Address: 232 GIVEN TCE, PADDINGTON,  
QLD, 4064; Victim 1: DOMINOS PIZZA PADDINGTON;  
Victim 2: BELLE PROPERTY;

Narrative:  
MO

At the nominated time and date a fire was reported to be occurring in the Dominos Eatery located in Given Terrace Paddington. The location is a building shared by 2x tenant businesses. QFRS attended and extinguished the fire in the Dominos victim business. QFRS were required to force entry through the front door of the second victim business (Belle Property) as smoke was observed inside. The QFRS Incident Commander stated that initial assessment of the location of the fire appeared to originate from the rear of Dominos where there is a electrical box. The fire has severely damaged the inside of the Dominos eatery. The Belle Property business only sustained smoke damage and damaged front door caused by QFRS effecting entry Fire investigators yet to attend and determine the likely cause of the fire. Initial fire response crews stated that they did not see any sign of forced entry. On speaking to the owner of Dominos, it was stated that staff left the property at 1:am It was stated that there was water leaking through the roof which caused the power to go out. It was stated that the staff intended to leave the issue until the morning. QFRS Incident Commander stated that the water leak appeared to be above the electrical box which is likely to have caused the fire.

Fire report MO details

The location is a building shared by 2x tenant businesses. QFRS attended and extinguished the fire in the Dominos victim business. QFRS were required to force entry through the front door of the second victim business (Belle Property) as smoke was observed inside. The QFRS Incident Commander stated that Initial assessment of the location of the fire appeared to originate from the rear of Dominos where there is a electrical box. . Fire suppression activity: N/A. Were other fires occurring in the area at the time: No. Have similar fires been occurring in the general or wider area: No. Were any fire warning in force at the time: No. Do you think this may be the act of a recidivist offender : No.

## GENERAL REPORT

At the nominated time and date a fire was reported to be occurring in the Dominos Eatery located in Given Terrace Paddington. The location is a building shared by 2x tenant businesses. QFRS attended and extinguished the fire in the Dominos victim business. QFRS were required to force entry through the front door of the second victim business (Belle Property) as smoke was observed inside. The QFRS Incident Commander stated that Initial assessment of the location of the fire appeared to originate from the rear of Dominos where there is a electrical box. The fire has severely damaged the inside of the Dominos eatery. The Belle Property business only sustained smoke damage and damaged front door caused by QFRS effecting entry Fire investigators yet to attend and determine the likely cause of the fire. Initial fire response crews stated that they did not see any sign of forced entry. On speaking to the owner of Dominos, it was stated that staff left the property at 1:am It was stated that there was water leaking through the roof which caused the power to go out. It was stated that the staff intended to leave the issue until the morning. QFRS Incident Commander stated that the water leak appeared to be above the electrical box which is likely to have caused the fire. . SOC not required.

Fire type

Property type damaged: Building/structure. Linked to other offences: No. Type of location: Commercial. Injury: No. Death: No.

Fire cause

Non-suspicious - non suspicious - Caused by rain water leaking onto electrical box. Human activity: N/A. Additional descriptors: N/A. Juvenile activity: No. Accelerant: No. Incendiary device: No.

Scene management and investigation

Who attended: Unknown. Cause and origin investigation: Yes - QFES. Crime scene: Not declared.

Fire origin

Origin/s of fire: Approximately known - rear of building at electrical box.

Insurance details

Property Insured: Unknown.

Financial status

Property offered or intended for sale: No. Mortgage or finance: Unknown. Money owed: Unknown.

Section 462 Criminal Code - Endangering particular property by fire

Damage to other s461CC property: No. Other section s461CC property endangered: No.

**Supplementary report**

Occurrence: QP2102188867 Fire - Building - Non Suspicious [0915] @24/11/2021 05:53 (232 GIVEN TCE, PADDINGTON, QLD Australia 4064 (Patrol group: CITY CENTRAL, Court Dist./Div.: BRISBANE/CENTRAL, Region: BRISBANE, District: NORTH BRISBANE, Division: BRISBANE CITY, Sta

Task: T2105874707 [Init rpt - Closed] Due: 10/12/2021 12:09 #4028996 DAVIDSON, K. ->#4028996 DAVIDSON, K. [Low] QPS Investigative Task Workflow Initial Report Task and Start Point QP2102188867 Fire - Building - Non Suspicious [0915] @24/11/2021 05:53 (232 GIVEN #4028996 DAVIDSON, K.

Author: #4028996 DAVIDSON, K.

Report time: 09/12/2021 12:09

Entered by: #4028996 DAVIDSON, K.

Entered time: 09/12/2021 12:09

Remarks: Public Report Update

Narrative: <p>Policelink has been contacted by an authorised person and/or business representative. The informant

has been verified as [Sch4p4(6)], DOB: [Sch4p4(6)]</p><p></p><p>The informant has stated they would like to: , request their report number</p><p></p><p>Property: There is no property to add</p><p></p><p>Additional information provided: Informant [Sch4p4(6)] contacted Policelink requesting the report number for this occurrence for insurance purposes.&nbsp;&nbsp; QP provided. No further information can be supplied by the informant.</p><p></p><p></p><p></p><p>NO REQUEST FOR POLICE ATTENDANCE SENT</p><p>COVID-19 QUESTIONS ASKED: NO RISK IDENTIFIED</p><p></p>

---

QPS RTI & PRIVACY UNIT



# Brisbane Region Daily Occurrence Log

City Central Patrol Group

For 24hrs starting 0600HRS on:

Wednesday, 24 November 2021



SHIFT	TEAM	SUPERVISOR (B400)	DUTY SGT (B229)
0600HRS - 1600HRS	Delta	▼ A/SGT WATKINS	▼
1400HRS - 2359HRS	Bravo	▼ A/SGT BASSINGTHWAIGHTE 4030897	▼ A/SGT COOPER 4031275
2000HRS - 0600HRS	Alpha	▼ SGT LALLY 4018150	▼

**PLEASE NOTE:**  
A NEW COLUMN HAS BEEN ADDED TO THE STATS SECTION BELOW TO CAPTURE CORONAVIRUS RELATED STATISTICS  
EACH SHIFT SUPERVISOR WILL BE RESPONSIBLE FOR ENTERING THESE TOTALS

## SIGNIFICANT EVENTS

No: TIME SIG EVENT MESSAGE No.

1 07:26

Sig Event Details:

Insert item

*Provides SGT BEN JOHNSON.*

## OCCURRENCES

No. TIME OCCURRENCE CATEGORY: OCCURRENCE TYPE:

1 04:25 400 - FIRE ▼ 401 FIRE BUILDING

QP2102188867 COPY YOUR DETAILS BEFORE CHANGING OCCURRENCE TYPE

DETAILS:

Job: 343

Incident Location: Domino's Pizza - 232 Given Tce, Paddington

Inf: QFRS

Business Owners: Sch4p4(6) & Sch4p4(6)

Units Inv: NC160, NC400, NC421, NC320, NC886, NC888, QFRS, Brisbane Traffic Mgr

Reporting Officer: S/C PRESTON

In details: Police were called by QFRS RE Fire at the IL. Police tow QFRS and established that the Fire was non-suspicious within IL. Traffic diversions required/implemented. QFRS had to break into IL to extinguish fire. Adjoining business BELLE Property front door had to be damaged to allow for QFRS to assess and allow smoke to ventilate. BO Sch and Sch4n stated that around 1am water was leaking through the ceiling and then the electricity went out. Decision was made to rectify in daylight. QFRS confirmed that the water had egressed onto teh electrical box causing the fire. Extensive damage to IL. Fire deemed Non-Suspicious.

QP2102188867

Click here to attach a file

No. TIME OCCURRENCE CATEGORY: OCCURRENCE TYPE:

2 00:00 ▼

QP

DETAILS:

Click here to attach a file

• BUDHAKA UNDA K816.  
• UNDA INKOTI PTO CUKALAS

BELLE Pabon

(M)

Sch4p4(6)

Sch4p4(6)

2/2102 188 867.

S.73 Irrelevant



9.45.  
SIRU

9.55

S/K  
CEROGTO

1335



24/9/21

WEB

NCHS

CP-3P

Blastings - MUM SET JOHNSON

TEAM CP = 3P  
2 x L.M.S , 3 x BOAT

THURS. ISSUES TEST.

QPS RTI & PRIVACY UNIT



No. H 156647

PRIVACY UNIT

24/11/21

44

Fire  
 Domino's  
 Labroke Terrace, Loddington  
 SN 343

Occ 14:25

Affected  
 Belle Property  
 232 Labroke Rd

Fire originated in  
 back of Domino's  
 which is severely  
 damaged.  
 Smoke travelled  
 into Belle property

45

through roof space  
 forced entry  
 through glass door

Key holders  
 Domino's

Sch4p4(6)

Belle Property

Sch4p4(6)





RTI & PRIVACY UNIT  
OPS

MAXIMUM  
taste  
NO SUGAR

